

NF35 SO-DIMM Testing

Type	Brand / Vendor	PN / Component	Size	1=SS	86 V420 + &
				2=DS	DIMM 1
1066	A-DATA /Micron	SU3S1066B2G7-R / 9MF27D9KPV	2G	2	Fail
1066	Apacer	AM5D5808M9J-9F / AS02GFA06C7N	2G	2	OK
1066	Apacer	AS01GFA06C7NBGC / AM5D5808AEWSB	1G	2	OK
1066	Elixir	M2N2G64CB8HA5N-BE/N2CB1G80AN-BE	2G	2	OK
1066	E-Point / Hynix	H5TQ1G83AFP / M32288-1BS	2G	2	Fail
1066	Kingston	KVR1066D3S7/1G / D1288JPNDPLD9U	1G	2	Fail
1066	Kingston / Hynix	KVR1066D3S7/2G / H5TQ1G83BFR	2G	2	Fail
1066	Samsung / SEC	M471B5673EH1-CF8 / K4B1G084GE	2G	2	OK
1066	Samsung / SEC	M471B5673FH0-CH9 / K4B1G084GF	2G	2	OK
1066	Transcend	JM1066KSU-2G / TK243PDF3 T0942	2G	2	OK
1066	Transcend / ELPIDA	TS128MSK64V1U / J1108BASE-AE-E	1G	1	OK
1066	Transcend / Hynix	TS256MSK64V1U / H5TQ1G83BFR	2G	2	OK
1066	Winchip	GDF2GB18S180C7 / AFE128EEV-10	2G	2	OK
1066	Wintec / hynix	3AM1066N3 / H5TQ1G83TFR	2G	2	OK
1066	Wintec / hynix	3AM1066N3 / H5TQ1G83TFR	1G	1	Fail
1066	Wintec / Hynix	3AM1066N3-1G / H5TQ1G83BFR	1G	2	OK
1333	ADATA	AD3S1333C2G9 / 3BCD-1508H	2G	2	Fail
1333	ADATA	AD3S1333C2G9 / 3BCD-1509H	2G	2	OK
1333	ADATA	AD3S1333C4G9-R / 3CCA-1509A	4G	2	OK
1333	ADATA / hynix	SU3S1333B2G9-B / H5TQ1G83BFR	2G	2	OK
1333	Apacer / hynix	78.A2GC6.AF1 / H5TQ1G83BFR	2G	2	OK
1333	Apacer / hynix	78.B2GC9.AF1 / H5TQ1G83BFR	4G	2	OK
1333	AVEXIR	AVD3S13330902G-1SW/AD3EE2568E-14	2G	2	OK
1333	Corsair	CMSO2GX3M1A1333C9 / 128M6DCJG	2G	2	OK
1333	Crucial / Micron	CT12864BC1339 / OMDD9LGO	1G	1	OK
1333	Crucial / Micron	CT25664BC1339 / OLDD9L GK	2G	2	OK

1333	Elixir	M2S2G64CB88B5N-CG / N2CBC2G80BN-CG	2G	2	Fail
1333	G.SKILL / Qimonda	F3-10666CL9S-2GBSQ/IDSH1G-03A1F1C-13H	2G	2	OK
1333	Kingston	KVR1333D3S9 / D1288JEMFPGD9U	2G	2	OK
1333	Kingston	KVR1333D3S9 / D1288JPNDPLD9U	2G	2	OK
1333	Kingston	KVR1333D3S8S94G / D2568JENC PGD9U	4G	2	OK
1333	Kingston / ELPIDA	KVR1333D3S9/2G / J1108BDBG-DJ-F	2G	2	Fail
1333	Kingston / hynix	KVR1333D3S8S92G / H5TQ2G83BFR	2G		Fail
1333	Kreton	KTH200S00815-1333A / KH2G8B335415	2G	2	Fail
1333	Kreton	KTH200S00825-1333A / KH1G8B335415	2G	2	OK
1333	Micron	MTBJSF12864HZ-1G1F1	2G	2	OK
1333	PATRIOT	PSD34G13332S / D9MGJ	4G	2	OK
1333	SAMSUNG	M471B5673FH0-CH9 / K4B1G0846F	2G	2	OK
1333	Team	TSD32048M1333C9-E / T3D1288LT-13	2G	2	OK
1333	Team / hynix	TSD32048M1333C9-E / H5TQ1G83TFR	2G	2	OK
1333	Transcend	M1333KGN-2G / TK483PCW3	2G	2	OK
1333	Transcend	SCDIMM CL9 / OND12D9LGK	2G	2	Fail
1333	Transcend / Micron	TS256MSK64V3N / OODD22D9LGK	4G	2	OK
1333	Transcend / Micron	TS256MSK64V3U / M9BD22D9JNM	2G	2	OK
1333	Transcend / Micron	TS512MSK64V3N / OND22D9LGK	2G	2	OK
1333	Transcend / SEC	TS128MSK64V3U / K4B1G08460	1G	1	OK
1333	Winchip	Winchip / AFN258EES-13	2G	2	OK
1600	ELPIDA	EBJ20UF8BCS0-DJ-F / J1108BFBG-DJ-F	2G	2	OK
1600	hynix	HTM351S6BFR8C-PB / H5TQ2G83AFR	4G	2	OK
1600	NANYA	NT4GC64B8HBONS-DI / NT5CB256M8BN-CG	4G	2	OK
1600	SAMSUNG	M471B5273CH0-CK0 / K4B2G0846B-HCH9	4G	2	OK